

5/04/051

3809 REPORT OF INSPECTION

Date: May 5, 2005 Time: about 2:00 pm Location: T.3S., R.21E., Sec. 29 NWNW

Operator(s) present during inspection: No (accompanied by Dan Gilfillan of the VFO)

Serial no. of notice: UTU 66366 (Dale Stevens expired project area) Is the operation active? No

Description of operations (including access, reclamation, etc.): The operator had filled the shallow excavation at the base of a rock ledge (see image 1 below, compare with image 1 of prior inspection). The scattered pile of wood and a few tires nearby (image 2 below) has yet to be removed.



image 1 – filled opening



image 2 – pile of material nearby

Is the operation in compliance with the notice on file and/or the stipulations of the approved plan? (if No describe deficiencies): Generally yes. The excavation has been filled. The case can be closed when the pile or material nearby is removed (onto the nearby private land owned by the operator of record). A letter encouraging this will be sent.

signature

print name/title

date

Inspector

original signed

Peter Sokolosky/Geologist

May 10, 2005

Management

original signed

Howard Cleavinger/AFFMMR

May 10, 2005

acknowledgement

cc: copy to UDOGM